Portkeys

5"

72MM

136MM

18.3MM

PT5II
User Manual

Battery Plate Lock

HDMI Input — Power Switch
Audio Headphone Output — USB Interface 5V In
HDMI Output — DC 7 ~ 24V Power Supply

1/4" Threaded Insert

SHENZHEN PORTKEYS
ELECTRONIC TECHNOLOGY CO.,LTD

Packing List

1 x PT5 II Monitor   1 x Pair of Rubber Covers
1 x MH-2 Mount   1 x User Manual
1 x HDMI to HDMI Cable   1 x Safety Box
1 x Micro HDMI to HDMI Cable   1 x Sunshade

UI Operation Logic

Tap the screen, swipe left or right, cycle through the shortcut function interface and the image setting interface.


(Shortcut Function Interface)

(Main Menu Interface)

How to get in icon functions

Click the icon to turn on the function; click the icon again to turn off the function.


Long press the icon, the setting interface shows at the bottom.

Click the icon, the setting interface shows at the bottom of the UI.

Hold the icon and slide to enter the shortcut functions menu.

Click the icon to get in the shortcut functions menu.

There are two ••• in the bottom setting interface, which means you can turn to the next page.

Click to return to the previous page.

3D LUT Loading and Deleting

Click icon, 3D LUT setting interface shows at the bottom, select Stored from USB, click the 3D LUT file to use the 3D LUT file.

Load the 3D LUT file into the U disk, plug it into the monitor USB port.

3D LUT   Stored from USB   USB Looks   Reset LUT

Click USB Looks to enter the corresponding location of the U disk and load the 3D LUT file.

Click Stored from USB, select the 3D LUT file, hold and swipe up, select "Yes" to delete the 3D LUT file.

Firmware Upgrade

Unzip the firmware package to the root directory of the U disk.

Please make sure not to power off during the upgrade process.

Compatible with USB flash drives in FAT, FAT32, ExFAT and NTFS formats. (FAT32 is recommended)

Please use a U disk with storage capacity below 16G.

PT5-V3.04.09   10Min   Update(USB)
Version Information   Run Time

Click the icon to get in the firmware upgrade interface, select Update(USB).
Select "Yes" to upgrade the firmware.

Shortcut Function Icons

Peaking	Rectangle Crop
Zebra	HDR(HLG)
False Color	Check Field
Luma Waveform	Guides
RGB Waveform	Cross Hair
Audio Meters	Grids
Luma Histogram	Add Shortcut Function
3D LUT	Delete Shortcut Function

Bottom Settings Area Icon

HDMI Input Signal Resolution	Backlight
After Date Loading Before/After 3D LUT	Enter the shortcut function selection interface
Off 3D LUT Switch	Enter the shortcut function setting interface

Main Menu Icon

Image Setting	3D LUT
Image and Menu Flip Settings	Volume Setting
System Setting	View version information and firmware upgrades